D G 1 UPS H

Accuracy ±1.0

Input current 0A~100A

Output 0V~5V

Output load 20k

Working frequency withstand voltage AC3kV/min.1mA

Working condition Temperature 0 ~45 Humidity 20%RH~95%RH 0 without condensation

Power supply DC±12V±8%


Power consumption 1W


External dimensions 53±0.5mm×16±0.5mm×69±0.5mm


Terminal definition

1 1 Tf5.)Tf-2535.8anod 2133 T70 T0 Tw2

mm







ч M4 Â

Adopt setscrew for installation, screw size is M4.

Þ à Ŧ Þ ’

Power supply and output terminals should be connected correctly;

ɢ ʜ ɢ ᵝ Þ Þ Ƙ Ƨ ʎ ɳ ’

Avoid to adjust the two potentiometers; use small screwdriver to screw it slowly to the precision when necessary;

ʌ Þ 60Ņ’

The temperature of ary generatrix should not over 60Ņ;

ʌ ɡ ’

The best measuring precision is obtained when the ary hole is full of current generatrix;

ą ɢ 2500 Â

The operating environment allows no electric dust or gases that corrodes metal or destroys insulation. The altitude is less than 2500m.

Note: The above pictures are for reference only, the products are subject to the actual product

Copyright, all rights reserved. Specification subject to change without prior notice.

Addr YADA Industrial Park,Gaopugang ,Heyuan City, Guangdong
TEL 86-762-3493888 FAX 86-762-3493912 POST 517000
http://www.yada.com.cn E-mail: market@yada.com.cn